


Photo Documentation of Spit Erosion




2022: Kachemak
Bay waves topping
the rock
revetments
protecting Homer
Spit Road.






Bank scouring on Homer Spit, where a City Campground was eroded away in 2019. Ocean Shores Boardwalk in the background.




By 2022, bank erosion had extended to the Ocean Shores Boardwalk, causing in 2023 the potential condemning of this commercial property.




Erosion is impacting utility installations on the Homer Spit. The City of Homer has had to repair and reposition utilities annually.

Homer Oyster Cooperative building in distance in photo.



Storm surge event on Homer Spit affecting the Homer Oyster Cooperative.



Bank erosion is threatening foundational piers on commercial properties.



The City of Homer has placed dredge materials at this site to partially reclaim a city campsite area on the Homer Spit. The placement of this material also provides a buffer for the highway embankment in this area.

The utility light pole shown in this photo was exposed 10 feet more between 2018 and 2019.



